



5.00 acre Parcel 102-43-005C. Features are NOT drawn to scale.

WELL INSPECTION REPORT

ADWR Well Registration No.: 55-224227
Well type: Exempt

Date drilled: 6-22-2015
Date of inspection: 7-7-2015

Drilled and inspected by: R. Davis Drilling LLC
PO Box 1427, Springerville, AZ 85938
(928) 245-0603

Well owner: James Wayne Crosswhite
Landowner: James Wayne Crosswhite Trust
PO Box 44, Nutrioso, AZ 85932
(928) 339-4840

Well location: Hse #2, CR 2112, 5 acres with shop, Nutrioso, AZ
GPS N33* 58.274' W109* 12.230'
T7N,R30E,S29,SW1/4,NE1/4,NE1/4
Parcel ID #102-43-005C, Apache County

Primary Use: Domestic

Casing type and diameter: Surface seal: 6" steel; well: 6" steel; perforated 60-80 ft

Total well depth: 103 ft (0-67 ft clay & silt), 65-80 ft (sand & gravel with water),
80-103 (sandstone)

Static water level: 50 ft

Pump rating (HP and flow): ½ HP 10 gpm Grunfaus pump on 1" galv pipe.

Pressure tank capacity: None

Overall mechanical condition: Operational on 220 volts

Overall visual condition: OK

Measured well flow rate: flows 10 gpm (fills 5 gal bucket in 25 sec from faucet)

Total well drawdown: est. 10 ft

Clarity of water: clear

Additional Remarks: Flow tested from faucet while operating pump with generator
See attached photos of drilling hole, setting pump, flow rate

Developing water well on 5 acres



6/22/15 Drilling



Drilling



Drilling



Drilling – groundwater blowing out of hole



7/7/15 Hole is cased with 6 inch steel pipe



Setting pump on 1" pipe



7/22/15 Operating pump with generator

Test flow rate

